



SLAB FFL. 44.900  
CAST IN PLATES CCP2 AT COLUMN LOCATIONS NOMINATED  
ALL OTHER COLS. BOLTED TO STEEL UNDER SECOND FLOOR SLAB (BALCONY COLS. WELDED TO EDGE BEAMS)

[illegible]